

Oil Field Environmental Incident Summary

Incident: 20140120181619

Date/Time of Notice: 01/20/2014 17:54

Responsible Party: Arrow Pipeline, LLC

Well Operator:

Well Name:

Field Name:

Well File #: 0

Date Incident: 1/20/2014

Time Incident: 14:45

Facility ID Number:

County: DUNN

Twp: 148

Rng: 92

Sec: 5

Qtr: NW

Location Description: 47 degrees, 40 min, 21 sec N, -102 degrees, 26 min, 09 sec W:

Submitted By: Don Butler

Received By:

Contact Person: Don Butler

c/o Crestwood Midstream Prtrs LP 801 Cherry Str
Suite 3800/Unit 20
Fort Worth, TX 76001

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

natural gas & natural gas condensate

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

est 100-ft wide x 240-ft length

Potential Environmental Impacts:

Action Taken or Planned:

Company personnel and response crew mobilized, gathering line was blocked in, pressure blowing down, repair and remedial actions to follow

Wastes Disposal Location:

Agencies Involved: MHA Environmental, MHA Safety

Updates

Date: 1/21/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill occurred within the MHA nation borders. Forwarded to BIA/Tribal authorities.